

Setup

Please follow these instructions:

1. Turn off your device.

2. Connect a jumper cable between G23 and GND on the expansion board.

3. Connect the expansion board to the computer using the USB cable.

Notes: Looking at the device with the LED on the top side G23 is the 4th pin from top on the left side.

GND is the 2nd pin from top on the right side.

In case you don't have an expansion board available, you need to connect the device to the computer using a serial port, and also perform step 2.







